



1

**Description**:

Entry monument



Photo Number

2

**Description**:

Exit gate and support





3

**Description**:

Entry gate support



Photo Number

4

Description:

Exit gate





5

**Description**:

Typical gate operator



Photo Number

6

**Description**:

Gate operator label





<u>Description</u>: Keypad gate controller



Photo Number

8

<u>Description</u>: Entry gate





9

**Description**:

Entry gate concrete pad deterioration



Photo Number

10

Description:

Pedestrian entry





<u>Description</u>: Mailboxes



Photo Number

**12** 

<u>Description</u>: Mailboxes





<u>Description</u>: Corroding anchor bolts on mailbox base



Photo Number **14** 

<u>Description</u>: Mailbox label





<u>Description</u>: Peeling mailbox paint




Photo Number **16** 

<u>Description</u>: View toward entry





<u>Description</u>: Cracked sidewalk near entry



Photo Number **18** 

Description:

Steel and stone fence at entry





<u>Description</u>: Vinyl fence and sidewalk along Mission St.



Photo Number **20** 

<u>Description</u>: Vinyl fence





Description:

Damaged area of vinyl fence



Photo Number **22** 

**Description**:

Ponding water on Terrace Lane





<u>Description</u>: Area of excessive moisture



Photo Number **24** 

**Description**:

Lower common area swale





<u>Description</u>: Broken asphalt and fine cracks



Photo Number **26** 

<u>Description</u>: Area of ponding





<u>Description</u>: Small broken asphalt area



Photo Number **28** 

<u>Description</u>: Runoff drain





**Description**:

Lower common drainage area



Photo Number

30

**Description**:

Runoff drain with stones inside